Technical.bulletin valeo added IIIIIII

CL-034

2012

Clutch Plate I Damaged Drive Plate Clutch


Damaged Drive Plate

Valeo Service Warranty Department have received clutch and flywheel kits where damage has been inflicted on the clutch plate and this part cannot be used.

After investigating the damage the cause has been traced to the clutch drive plate coming into contact with the locating dowels on the flywheel. This issue will occur if the kit is not transported correctly.









Valeo clutch kits sold with flywheels MUST ALWAYS be transported and stored horizontally. If the kit is transported vertically, the clutch cover could become detached from the flywheel and allow the drive plate to move between the two parts.



