


The Problem

Valeo technical have received some calls regarding the difference between central slave cylinders (CSC) 804528 and 804549 for the Mercedes Sprinter 1995 – 2006.

CSC 804549 is for vehicles fitted with the sprint shift (semi automatic) gearbox. On 804549 there is a height sensor so the gearbox can recognise when the clutch is fully engaged. 804528 are for vehicles fitted with a conventional manual gearbox.

To determine which CSC the customer needs, if the vehicle has a clutch pedal the CSC needed will be 804528.

Below are pictures of 804549 and 804528 with the differences labelled.



804528 – CSC for manual gearbox

Manual
gearbox,
no height
sensor



804549 – CSC for semi automatic gearbox

CSC height
sensor

T.S.B. No.:
CL020/09

PRODUCT:
Clutch

MARQUE:
Mercedes Sprinter
1995 – 2006

PART No.:
804528, 804549

SUBJECT:
The difference
between central
slave cylinders (CSC)
804528 and 804549
for the Mercedes
Sprinter 1995 – 2006

DATE:
October 2009