


## The Problem

The Valeo technical department have produced a bulletin to recognise the differences between the CSC's 804539 and 804543 so the correct part can be provided and a returned unit can be verified it has the correct part number on it.

The reason for the differences between the 804539 and 804543 is the cylinder bore inside the CSC.

804539 has a cylinder bore of 28 mm and 804543 has a cylinder bore of 24.9 mm, which will mean 804539 will need a greater amount of fluid to move the piston compared to 804543.

Below are pictures of the two CSC's and how to identify each of them.



**T.S.B. No.:**  
CL023/09

**PRODUCT:**  
Clutch

**MARQUE:**  
All

**PART No.:**  
804539, 804543

**SUBJECT:**  
Differences between 804539 and 804543 which are difficult to determine

**DATE:**  
November 2009