










<b>ABS SENSORS</b>		
<b>90313</b>	<b>90314</b>	<b>90315</b>
CHEVROLET 96473221	CHEVROLET 96473222	CHEVROLET 96473223
		
CHEVROLET AVEO, KALOS 1.4	CHEVROLET AVEO, KALOS 1.2	CHEVROLET AVEO, KALOS 1.4
<b>90316</b>	<b>90317</b>	<b>90318</b>
CHEVROLET 96549713	CHEVROLET 96549712	CHEVROLET 96569341
		
CHEVROLET LACETTI, NUBIRA 1.6	CHEVROLET LACETTI, NUBIRA 1.8	CHEVROLET MATIZ 1.0
<b>90319</b>	<b>90320</b>	<b>90321</b>
CHEVROLET 96569342	CHEVROLET 96457295	CHEVROLET 96456815
		
CHEVROLET MATIZ 0.8	CHEVROLET MATIZ 1.0	CHEVROLET MATIZ 0.8
<b>90322</b>		
CHEVROLET 96456816		
		
CHEVROLET MATIZ 0.8		

<b>CAM &amp; CRANKSHAFT SENSORS</b>		
<b>87591</b>	<b>87592</b>	<b>87596</b>
SUBARU 22060AA070	JEEP 56027865	HYUNDAI/KIA 3931002200
		
SUBARU FORESTER, IMPREZA, LEGACY 2.0	JEEP CHEROKEE, WRANGLER 4.0	KIA PICANTO, HYUNDAI GETZ 1.1
<b>EGR VALVES</b>		
<b>88138</b>	<b>88229</b>	<b>88230</b>
FIAT 504373660	TOYOTA 2562027090	TOYOTA 2580026010
		
FIAT DUCATO 3.0 D	TOYOTA COROLLA 2.0 D	TOYOTA RAV 4 III, AVENSIS 2.2 D
<b>88231</b>	<b>88232</b>	
TOYOTA 2562033030	TOYOTA 2580033011	
		
TOYOTA YARIS 1.4 D	TOYOTA IQ, AURIS, YARIS 1.4 D	
<b>FUEL PUMP</b>	<b>INJECTOR</b>	
<b>77341</b>	<b>75112523</b>	
VW 6R0919050R	FIAT 9945561	
		
SEAT IBIZA, VW POLO tdi	FIAT PUNTO 1.2	

IGNITION COILS		
<b>10363</b>	<b>10658</b>	<b>10687</b>
AUDI 078905101C	NISSAN 224481KT0A	FIAT 55231256
		
AUDI A4 2.6, A8 2.8	NISSAN JUKE, CUBE 1.6	FIAT 500, LANCIA YPSILON 0.9
<b>10713</b>	<b>10715</b>	<b>10718</b>
RENAULT 224332428R	JAGUAR LCA1510AB	TOYOTA 9008019027
		
RENAULT MEGANE III 1.2, GRAND SCENIC III 1.6	JAGUAR XK8 4.0	TOYOTA LAND CRUISER 4.7, LEXUS IS 200
<b>10752</b>		
MERCEDES 1561500080		
		
MERCEDES E-Class, S-Class AMG		
LPG FILTERS		
<b>4995</b>	<b>4996</b>	<b>4997</b>
FIAT 41565341	FIAT 60657348	FIAT 71771247
		
FIAT DOBLO, DUCATO, QUBO 1.4 Natural Power	FIAT PUNTO, PANDA 1.2	Fiat models with CNG supplies

OXYGEN SENSORS		THROTTLE BODY
<b>81743</b>	<b>81744</b>	<b>89154</b>
PSA 9683265480	PSA 7548961, BMW 11787548961	RENAULT 7701051585
		
CITROEN C4, PEUGEOT 308 1.6 hdi	CITROEN C3 1.4, PEUGEOT 206 1.4, MINI COOPER S	RENAULT CLIO, TWINGO 1.2
PULLEYS		
<b>45233</b>	<b>45234</b>	<b>45235</b>
TOYOTA 27415-33060	NISSAN 23151-5X21A	OPEL 12 04 293
		
TOYOTA YARIS 1.4 D	NISSAN QASHQAI 1.6	OPEL CORSA, MERIVA 1.2
<b>45240</b>	<b>45241</b>	
HYUNDAI/KIA 25290-2A000	INA 400 0338 10	
		
HYUNDAI i20, KIA RIO 1.4	TOOL	
VACUUM PUMPS		
<b>91100</b>		
VW 068145101EX		
		
VW GOLF I,II 1.6 D, TRANSPORTER III 1.6 D		