

Technical Services Bulletin

The Problem

CSC with part number 804501 has had a design change and it has been identified that the newer version will not fit vehicles built before 08/1998 due to the quick release connector not fitting through the holes on the gearbox.

Below are pictures of the old and new versions of 804501 with the differences shown.





Old version of 804501 - Aluminium body

New version of 804501 - Plastic body

The new design of 804501 will not fit vehicles with a 17mm diameter hole in the gearbox. This gearbox was originally fitted to vehicles built before 08/1998.

Below is a list of all of the vehicles that are affected by the change in design of 804501. Dates highlighted in bold are the dates that the new version of 804501 will fit.

•			cc	KW	20		<i>2</i>		L	€÷,	2	
FORD	Courrier (95>)	1.3i	1299	44	J6C	821117	10/96	09/02	834006	804501	65/98	09/02
FORD	Courrier (96>)	1.6i	1556	70	21.16	825492	07/99		834038	804501	07/99	
FORD	Courrier (95>)	1.80	1763	44	RTJ	825043	10/96	09/02	834007	804501	66/98	09/02
FORD	Courrier (96>)	1.8TD	1753	55	CI-TD	829646	09/00		834057	804501	03/00	
FORD	Flesta (95>99)	1.0i	999	33	a	821117	05/96	04/99	834006	804501	05/96	04/99
FORD	Fiesta (95×99)	1.1i	1118	37	GBA	821117	10/95	09/96	834006	804501	13/95	09.96
FORD	Fiesta (95>99)	1.2i 16V	1242	55	CHA	821117	08/95	09/99	834006	804501	86/38	09.99
FORD	Flesta (95>99)	1.3i	1299	3744	J6C, JJA	821117	08/95	05/99	834006	804501	66/98	08/99
FORD	Flesta (95>99)	1.4i 16V	1388	66	FHA	821117	01/96	08/99	834006	804501	06/98	08.99
FORD	Flesta (95×99)	1.8D	1753	44	RTJ,RTK	825043	08/95	05/99	834007	804501	66/38	08/99
FORD	Flesta (99>2002)	1.2/167	1242	55	DHB, DHC	821117	08/99	03/02	834006	804501	08/99	03/02
FORD	Flesta (99×2002)	13	1259	3744	JAJ, JAL, JJC, JJE	821117	08/99	03/02	834006	804501	08/99	03/02
FORD	Fiesta (99×2002)	1.4:167	1368	66	FHA, FHE	821117	08/99	03/02	834006	804501	03/99	03/02
FORD	Flesta (99×2002)	1.6i	1566	70	ZL16	825492	10/99	03/02	834038	804501	13/99	03/02
FORD	Flesta (99>2002)	1.80	1753	44	RTJ	825043	09/99	03/02	834007	804501	09/99	03/02
FORD	Flesta (99>2002)	1.8TDdi	1763	- 55	CILTO, RTN, RTP, RTQ	829846	0200	03/02	834057	804501	02/00	03/02
FORD	Focus (98>2004)	1.4i 16V	1388	- 65	FXDA, FXDC	825048	10/98	10/03	834008	804501	13/98	10.03
FORD		1.6/167	1596	74	PYDA, FYDC, FYDD	829055	10/98	10/03	834009	804501	13/98	10.03
FORD	Focus (95>2004)	1.8 167	1795	85	EYDA, EYDC, ZH18	825055	10/98	10/03	834009	804501	13/98	10,03
FORD	Foous (98>2004)	2.0 167	1988	96	EDDA, EDDC	825062	10/98	10/03		804501	13/98	10.03
FORD	Ka	1.3i	1259		J4D, J4K, J4M, JJB, JJD, JJF, DURA13	821117	09/96	09/02	834006	804501	66/56	09/02
FORD	Puma	1.4(16)	1368	66	PHD, FHF	821117	01/98	10,00	834006	804501	66:98	10,00
FORD	Puma	1.6:167	1596	76	ZH16S	825492	09/00	1201	834038	804501	09/00	12/01
FORD	Puma	1.7/167	1679	92110	NHA, MHA-160	625044	05/97	1201		804501	66/98	12/01
MAZDA	121 (JAUB) (98×)	1.216V	1242	55	DHA	821117	03/96	05/02	834006	804501	00/98	05/02
MAZDA	121 (JAUB) (96>)	1.3	1299	3744	J6C, JJA	821117	03/96	05/02	834006	804501	86/38	05/02
MAZDA	121 (JAUB) (96>)	1.80	1753	44	RTK	825043	03/96	05/02	834007	804501	86/38	05/02

Please be aware that while the new version of 804501 will fit vehicles built after 08/98, there may be some cases where a later vehicle has had a gearbox change and an earlier gearbox is fitted.

T.S.B. No.: CL021/09

PRODUCT: Clutch

MARQUE: All vehicles

PART No.: 804501

SUBJECT:
Design change means that the newer version will not fit vehicles built before 08/1998

DATE: October 2009



www.valeoservice.co.uk





