



## Technical info

### Code: 86122

Meat&Doria's primary objective is to choose the best possible providers based on high quality standards. This specific product is part of a Bosch throttle body.

Sensor 86122 is removed from the throttle body in house.

The originality of the sensor can only be examined from the Bosch microchip found in the inside of the sensor. This microchip cannot be copied and it is not included in any other imitation or alternative product.

On the right photograph there is the original sensor with microchip distributed by Meat&Doria and on the left an imitation which usually only has a silicone cover.

Unfortunately, there is no other evident mark or logo on the sensor indicating that it is an original Bosch product.

If you have any further questions or problems, please contact our quality department.

